

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/08/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/03/12 – 0700, 05/10/12
7. Personnel Roster Assigned			
Name	ICS Position	Home Base	
Matthew Haak	Situation Unit Leader	Houston, Texas	
8. Activity Log			
Time	Major Events		
09:00	<p>Overflight Operational status:</p> <ul style="list-style-type: none"> • Source area pond, no sheen observed. • Frac-Tank City, footprint reduction continued. • Frac-Tank City, observed construction of the new decon pad. • Confluence, no turbidity or sheen observed. • OB2.75 RDB, sheen observed beneath tree. • MP2.75 LDB, new dock installed extending into the river. • Island A, sheen observed. • MP3.25, observed poling crew training. • MP4.5, observed poling crew training. • MP5.25, observed poling crew training. • MP5.5 RDB, sheen observed. • MP5.75 RDB, sheen observed. • Ceresco Dam control point, no sheen observed. • Ceresco Dam, legacy work continued. • MP7.5, sheen observed in the middle of the island. • MP10.75, sediment trap location. • MP13.5 LDB, sheen observed. • MP15.25 LDB, sheen observed. • Rock Tenn, sheen observed. • MP21.5 Custer Dr. RDB, sheen observed. • MP23.4, observed shoreline restoration work. • MP24.0, observed shoreline restoration work. • MP30.0, sheen observed at E2 boat launch. • MP30.8 containment boom, no sheen observed. • MP36.10, observed sediment trap installation. • MP36.5 LDB, sheen observed. • MP36.5, sheen observed prior to 35th Street Bridge. • MP37.75, sheen observed along control point. • MP37.75, sheen sweep boat sweeping around island on lake side of boom. • Morrow Lake, observed public fishing near dam. 		
	Additional observations: None		
15:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			